



交通部航港局航船布告

中華民國 112 年 10 月 13 日

633 礙航公告(中區)-更新巴拿馬籍商船XING SHUN NO.1 (鑫順1號))沉船相關資訊

依據 海歷企業股份有限公司 112 年 9 月 14 日海歷字第 1120914001 號函檢附之殘油完工報告。

說明 巴拿馬籍商船 XING SHUN NO.1 (鑫順1號)111 年 10 月 31 日主機故障漂流，並因不明原因進水後傾斜沉沒，112 年 4 月 29 日掃測之船體水深最淺處位於北緯 23°55'34.69" 東經 119°59'08.43"，深度更新為最低天文潮(LAT) 26.044 米。

位置 航經附近水域船舶請注意瞭望及避讓，以維航行安全。
北緯 23°55'34.7"，東經 119°59'08.4"。
北緯 23°55'36.6"，東經 119°59'10.0"。
北緯 23°55'33.5"，東經 119°59'07.7"。*WGS84

交通部航港局
局長 葉協隆



NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

October 13, 2023

633 Changhua Taiwan Around Waters-Chart and Depth Correction to Shipwreck
Cement Carrier XING SHUN NO.1

Source SEAGREEN MARINE SERVICE CO., LTD. in Oil Removal Survey dated on
September 14, 2023.

Details Oil Removal Survey conducted on September 14th, 2023 indicates that the cemen
t carrier, XING SHUN NO.1, sank in a depth of 26.044m(LAT) in the position of
23°55'34.69"N 119°59'08.43"E.

Mariners are advised to navigate with caution in the area.

Please refer to the attachment for more details.

Positions Lat. 23°55'34.7" N., Long. 119°59'08.4" E.
Lat. 23°55'36.6" N., Long. 119°59'10.0" E.
Lat. 23°55'33.5" N., Long. 119°59'07.7" E. *WGS84

Maritime and Port Bureau, MOTC
Director-General Yeh Hsieh-Lung