



交通部航港局航船布告

中華民國 113 年 7 月 11 日

409

礙航公告(中區)(113年8月1日至114年4月30日)臺灣港務股份有限公司臺中港務分公司「臺中港37、38號碼頭新建工程」航道及船席浚挖施工船機作業之海上工作安全警示計畫

依 據 臺灣港務股份有限公司臺中港務分公司 113 年 7 月 10 日 中港工字第 1134208
說 明 號函辦理。
臺灣港務股份有限公司臺中港務分公司「臺中港 37、38 號碼頭新建工程」航道及船席浚挖施工船機作業之海上工作安全警示計畫，詳細資料如附件。

航行船隻，請避開該區域，注意航行以策安全。

位 置 北緯 24°15'31.7"，東經 120°30'32.8"。
北緯 24°15'14.1"，東經 120°30'25.3"。
北緯 24°15'35.3"，東經 120°30'34.4"。
北緯 24°15'36.8"，東經 120°30'30.1"。
北緯 24°15'14.1"，東經 120°30'20.4"。
北緯 24°15'13.2"，東經 120°30'23.0"。
北緯 24°15'36.8"，東經 120°30'30.1"。
北緯 24°15'35.3"，東經 120°30'34.4"。
北緯 24°15'14.7"，東經 120°30'18.7"。
北緯 24°14'42.1"，東經 120°29'24.6"。
北緯 24°15'04.0"，東經 120°29'04.9"。
北緯 24°15'03.6"，東經 120°29'15.3"。 *WGS84

交通部航港局局長
葉協隆



NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

July 11, 2024

409

Taichung Port Pier 37 and 38 new construction project

Source Port of Taichung, Taiwan International Ports Co. Ltd., No. 1134208804 dated July 11, 2024.

Details The marine work safety warning plan for the new construction of Piers 37 and 38 in Taichung Port, detailed information is in the attachment.
Mariners are advised to navigate with caution in the area.
Please refer to the attachment for more details.

Positions Lat. 24°15'31.7" N., Long. 120°30'32.8" E.
Lat. 24°15'14.1" N., Long. 120°30'25.3" E.
Lat. 24°15'35.3" N., Long. 120°30'34.4" E.
Lat. 24°15'36.8" N., Long. 120°30'30.1" E.
Lat. 24°15'14.1" N., Long. 120°30'20.4" E.
Lat. 24°15'13.2" N., Long. 120°30'23.0" E.
Lat. 24°15'36.8" N., Long. 120°30'30.1" E.
Lat. 24°15'35.3" N., Long. 120°30'34.4" E.
Lat. 24°15'14.7" N., Long. 120°30'18.7" E.
Lat. 24°14'42.1" N., Long. 120°29'24.6" E.
Lat. 24°15'04.0" N., Long. 120°29'04.9" E.
Lat. 24°15'03.6" N., Long. 120°29'15.3" E. *WGS84

*Director General Hsieh-Lung, Yeh
Maritime and Port Bureau, MOTC*