



## 交通部航港局航船布告

中華民國 113 年 8 月 8 日

525

連江縣(北區)(113年8月8日)有關連江縣港務處函知馬祖南竿福澳港及西莒青帆港之導航燈浮因凱米颱風影響受損遺失，請進出港及航行附近水域之船舶，注意瞭望及航行安全。

依  
說

據  
明

依據連江縣港務處 113 年 8 月 8 日港管字第 1130002029 號函辦理。

一、依據連江縣港務處 113 年 8 月 8 日港管字第 1130002029 號函辦理。

二、有關設置於馬祖福澳港及青帆港之導航燈浮，因凱米颱風影響受損遺失，請進、出港及航經該水域船隻，請注意避讓。。

三、於下述位置燈浮標遺失：

福澳港燈浮標

26°09' 47.1" N 119°56' 25.3" E

青帆港燈浮標

25°58' 1.94" N 119°55' 48.47" E

25°58' 9.84" N 119°55' 41.98" E

位

置

北緯 26°09'47.1"，東經 119°56'25.3"。

北緯 25°58'01.9"，東經 119°55'48.5"。

北緯 25°58'09.8"，東經 119°55'42.0"。\*WGS84

交通部航港局  
局長葉協隆



## NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

---

August 8, 2024

**525** TAIWAN. North Area. - Lianjiang County Nangan Fuao Port□Xiju Qingfan Port light buoy missing. Mariners are advised to navigate with caution in this area.

Source Harbour Bureau OF Lianjiang County,letter No. 1130002029 dated August.8, 2024

Details The Light buoy missing in the mentioned position is  
Nangan Fuao Port 26°09'47.1"N 119°56'25.3"E  
Xiju Qingfan Port 25°58'1.94"N 119°55'48.47"E  
25°58'9.84"N 119°55'41.98"E

Positions Lat. 26°09'47.1" N., Long. 119°56'25.3" E.  
Lat. 25°58'01.9" N., Long. 119°55'48.5" E.  
Lat. 25°58'09.8" N., Long. 119°55'42.0" E. \*WGS84

*Director General Hsieh-Lung Yeh  
Maritime and Port Bureau., MOTC*