



交通部航港局航船布告

中華民國 113 年 11 月 8 日

707

礙航公告(中區)「彰芳暨西島離岸風場之風場維護作業」施工船舶更新案(113年11月15日至119年10月18日)

依據 彰芳風力發電股份有限公司 113 年 11 月 7 日彰芳風力字第 1131107002 號函
說明 風場作業期間維護工作新增船舶 Orient Constructor、並展延 MMA Prestige，相關資料詳如附件。

非計畫相關之工作船隻，請避開該區域，注意航行以策安全。

位置 北緯 24°02'46.3"，東經 120°12'49.0"。
北緯 23°57'29.1"，東經 120°08'57.3"。
北緯 23°57'50.1"，東經 120°03'59.1"。
北緯 24°02'44.1"，東經 120°07'46.8"。
北緯 23°59'04.5"，東經 120°11'06.3"。
北緯 23°58'52.7"，東經 120°12'20.5"。
北緯 23°58'43.1"，東經 120°12'13.9"。
北緯 23°58'02.0"，東經 120°11'43.1"。
北緯 23°57'11.3"，東經 120°10'58.3"。
北緯 23°57'04.8"，東經 120°10'52.1"。
北緯 23°57'15.4"，東經 120°09'46.6"。*WGS84

交通部航港局局長
葉協隆



NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

November 8, 2024

707

Changhua Taiwan Offshore-CFXD Offshore Wind Farm Maintenance Inspections

Source

Changfang Wind Power Co., Ltd., letter No. 1131107002 dated November 7, 2024.

Details

Mariners are advised that Changfang and Xidao Offshore Wind Farm shall commence maintenance inspections on or around November 15, and works are expected to be completed on October 18, 2030.

Mariners are advised to navigate with caution in the area.

Please refer to the attachment for more details.

Positions

Lat. 24°02'46.3" N., Long. 120°12'49.0" E.

Lat. 23°57'29.1" N., Long. 120°08'57.3" E.

Lat. 23°57'50.1" N., Long. 120°03'59.1" E.

Lat. 24°02'44.1" N., Long. 120°07'46.8" E.

Lat. 23°59'04.5" N., Long. 120°11'06.3" E.

Lat. 23°58'52.7" N., Long. 120°12'20.5" E.

Lat. 23°58'43.1" N., Long. 120°12'13.9" E.

Lat. 23°58'02.0" N., Long. 120°11'43.1" E.

Lat. 23°57'11.3" N., Long. 120°10'58.3" E.

Lat. 23°57'04.8" N., Long. 120°10'52.1" E.

Lat. 23°57'15.4" N., Long. 120°09'46.6" E. *WGS84

Director General Hsieh-Lung, Yeh
Maritime and Port Bureau, MOTC