



交通部航港局航船布告

中華民國 113 年 11 月 13 日

718

礙航公告(中區)(113年8月1日至114年4月30日)臺灣港務股份有限公司臺中港務分公司「臺中港37、38號碼頭新建工程」航道及船席浚挖施工船機作業之海上工作安全警示計畫更新施工船舶資訊

依據 臺灣港務股份有限公司臺中港務分公司 113 年 11 月 12 日中港工字第 1134214598 號函辦理。

說明 旨案新增本國籍宏益 1 號(Hung Yi No.1)、宏揚 1 號(Hung Yang No.1)、宏揚號(Hung Yang)、宏興 1 號(Hung Shing No.1)為作業船舶。

非計畫相關之工作船隻請避開該區域，注意航行以策安全，相關資料如附件。

位置 北緯 24°15'31.7"，東經 120°30'32.8"。
北緯 24°15'14.1"，東經 120°30'25.3"。
北緯 24°15'35.3"，東經 120°30'34.4"。
北緯 24°15'36.8"，東經 120°30'30.1"。
北緯 24°15'14.1"，東經 120°30'20.4"。
北緯 24°15'13.2"，東經 120°30'23.0"。
北緯 24°15'36.8"，東經 120°30'30.1"。
北緯 24°15'35.3"，東經 120°30'34.4"。
北緯 24°15'14.7"，東經 120°30'18.7"。
北緯 24°14'42.1"，東經 120°29'24.6"。
北緯 24°15'04.0"，東經 120°29'04.9"。
北緯 24°15'03.6"，東經 120°29'15.3"。*WGS84

交通部航港局局長
葉協隆



NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

November 13, 2024

718 Taichung Port Pier 37 and 38 new construction project

Source Port of Taichung, Taiwan International Ports Co. Ltd., No.1134214598 dated November 12, 2024.

Details The marine work safety warning plan for the new construction of Piers 37 and 38 in Taichung Port, detailed information is in the attachment.
Mariners are advised to navigate with caution in the area.
Please refer to the attachment for more details.

Positions Lat. 24°15'31.7" N., Long. 120°30'32.8" E.
Lat. 24°15'14.1" N., Long. 120°30'25.3" E.
Lat. 24°15'35.3" N., Long. 120°30'34.4" E.
Lat. 24°15'36.8" N., Long. 120°30'30.1" E.
Lat. 24°15'14.1" N., Long. 120°30'20.4" E.
Lat. 24°15'13.2" N., Long. 120°30'23.0" E.
Lat. 24°15'36.8" N., Long. 120°30'30.1" E.
Lat. 24°15'35.3" N., Long. 120°30'34.4" E.
Lat. 24°15'14.7" N., Long. 120°30'18.7" E.
Lat. 24°14'42.1" N., Long. 120°29'24.6" E.
Lat. 24°15'04.0" N., Long. 120°29'04.9" E.
Lat. 24°15'03.6" N., Long. 120°29'15.3" E. *WGS84

*Director General Hsieh-Lung, Yeh
Maritime and Port Bureau, MOTC*