



交通部航港局航船布告

中華民國 114 年 3 月 5 日

96 礙航公告(中區)海洋離岸風力發電場「離岸風機A06編號識別板
照明燈故障」

依據 海洋風力發電股份有限公司 114 年 3 月 4 日洋 T06 字第 1140200037 號
說明 海洋風場苗栗外海離岸風機編號 A06 識別板照明燈故障，惟因天氣因素無法立即執行維修，待修繕完畢將另行通知，請航經該附近水域船舶注意瞭望及避讓，以策安全。

離岸風機編號識別板照明燈位置如下：

風機編號 :A06

座標：東經 120°49' 35" E，北緯 24°43' 10" N

位置 北緯 24°43'10.0"，東經 120°49'35.0"。*WGS84

交通部航港局局長
葉協隆



NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

March 5, 2025

96

Miaoli Offshore-Wind turbine ID board lighting failure

Source

Formosa 1 Offshore Wind Farm, letter No. 1140200037 dated 4th March, 2025.

Details

The identification plate lighting of the offshore wind turbine A06, located off the coast of Miaoli, ID board lighting has malfunctioned.

However, due to weather conditions, immediate repairs cannot be carried out. A notification will be issued once the repair is completed.

Vessels passing through the vicinity to maintain vigilance and take necessary precautions to ensure safety.

Positions

Position: Wind turbine ID: A06 □ □ Location: 120°49'35" E, 24°43'10" N

Lat. 24°43'10.0" N., Long. 120°49'35.0" E. *WGS84

*Director General Hsieh-Lung, Yeh
Maritime and Port Bureau, MOTC*