

行政院農業委員會漁業署-全國水環境改善計畫

工程訪視紀錄表

訪查案件	蚵子寮漁港馬頭及景觀改造	
訪查時間	110年12月09日	
訪查結果		
評分 (25分)	22.5	<p>蚵子寮漁港_蚵子寮漁港碼頭及景觀改造工程</p> <p>Detailed description of the radar chart: The chart is a five-pointed star with five axes. The top axis is labeled '效益達成程度' with a score of 5. The right axis is '資訊公開完整性' with a score of 4. The bottom-right axis is '公民參與落實度' with a score of 3. The bottom axis is '生態檢核落實度' with a score of 2. The left axis is '後續維護管理成效' with a score of 2. The center of the chart is marked with 0, and concentric lines are labeled 1, 2, 3, 4, and 5.</p>
優點	舊有碼頭更新，大幅提升漁港整體環境品質，且板樁式碼頭對於港區水面靜穩度佳，設計成果正確。	
缺點	<ol style="list-style-type: none"> 1. 工程施工面維護不當。 2. 景觀工程為遮蔭棚架，名目有些不符。 3. 碼頭混凝土面相當粗糙，視覺觀感不佳，美化工作有待加強。 4. 缺乏漁網漁具置放場所，環境凌亂。 	