



## 交通部航港局航船布告

中華民國 112 年 5 月 10 日

### 259 礙航公告(中區)-更新巴拿馬籍商船XING SHUN NO.1 (鑫順1號) )沉船相關資訊

依據 本案 P&I 公司提供之詮華國土測繪有限公司 112 年 4 月 29 日鑫順 1 號掃測報告。

說明 一、巴拿馬籍商船 XING SHUN NO.1 (鑫順 1 號)111 年 10 月 31 日主機故障漂流，並因不明原因進水後傾斜沉沒，112 年 4 月 29 日掃測之船體水深最淺處位於北緯 23°55'34.69" 東經 119°59'08.43"，深度 24.645 公尺(最低天文潮)。

位置 二、請航行船隻注意瞭望並遠離，以維航行安全。  
北緯 23°55'34.7"，東經 119°59'08.4"。  
北緯 23°55'36.6"，東經 119°59'10.0"。  
北緯 23°55'33.5"，東經 119°59'07.7"。\*WGS84

備註 更新航船布告20230180。

交通部航港局  
局長 葉協隆



## NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

---

May 10, 2023

**259** Changhua Taiwan Around Waters-Chart and Depth Correction to Shipwreck Cement Carrier XING SHUN NO.1

Source SEAGREEN MARINE SERVICE CO., LTD. in Water Survey dated on April 29th, 2023.

Details 1. Water survey conducted on April 29th, 2023 indicates that the cement carrier, XING SHUN NO.1, sank in a depth of 24.645m in the position of 23°55'34.69"N 119°59'08.43"E.

2. Mariners are advised to navigate with caution in the area.

Positions Lat. 23°55'34.7" N., Long. 119°59'08.4" E.

Lat. 23°55'36.6" N., Long. 119°59'10.0" E.

Lat. 23°55'33.5" N., Long. 119°59'07.7" E. \*WGS84

Remarks Former Notice 20230180.

*Maritime and Port Bureau, MOTC  
Director-General Yeh Hsieh-Lung*