



交通部航港局航船布告

中華民國 113 年 1 月 18 日

32

礙航公告（北區）臺中港籍「富庭168號」漁船(CT4-3212)於北緯24度52分,東經122度03分,遭海釣船撞擊後翻覆,漁船殘骸海上漂流,目前漂流至北緯25度06分,東經122度08分。

依
說

據
明

依據海巡署艦隊分署第七岸巡隊113年1月17日航船布告傳真通報。

1、臺中港籍「富庭168號」漁船(CT4-3212)於宜蘭縣龜山島東北方6浬處:北緯24度52分,東經122度03分,遭基隆港籍「大統1號」海釣船(CT3-6122)撞擊後翻覆,人員安全救離,漁船殘骸海上漂流,目前漂流至三貂角東北方8.5浬處:北緯25度06分,東經122度08分。

2、請過往船舶注意瞭望及避讓,以維航行安全。

3、位置:

北緯24°52',東經122°03'

北緯25°06',東經122°08'

位

置

北緯24°52'00.0",東經122°03'00.0"。

北緯25°06'00.0",東經122°08'00.0"。*WGS84

交通部航港局
局長 葉協隆



NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

January 18, 2024

32 The fishing vessel Futing 168 (CT4-3212) was hit by a fishing boat at 24°52'N, 122°03'E and capsized, and the wreckage of the fishing boat drifted at sea, currently drifting to 25°06'N, 122°08'E

Source It shall be handled in accordance with the fax notice of the Seventh Coast Patrol of the Fleet Branch of the Coast Guard on January 17, 2024.

Details 1. Taichung-flagged fishing vessel "Futing No. 168" (CT4-3212) was 6 nautical miles northeast of Guishan Island, Yilan County: 24°52'N, 122°03'E, was hit by the Keelung-flagged "Datong No. 1" sea fishing boat (CT3-6122) and capsized, the fishing boat drifted at sea, and is currently drifting to 8.5 nautical miles northeast of Sandiao Jiao-Cape: 25°06'N, 122°08'E.

2. Passing ships are advised to pay attention to lookout and avoid to maintain navigation safety.

3. Position:

24°52'N, 122°03'E

25°06'N, 122°08'E

Positions Lat. 24°52'00.0" N., Long. 122°03'00.0" E.

Lat. 25°06'00.0" N., Long. 122°08'00.0" E. *WGS84

*Maritime and Port Bureau, MOTC
Director-General Yeh Hsieh-Lung*