



交通部航港局航船布告

中華民國 113 年 5 月 1 日

232

礙航公告(中區)(即日起至116年3月11日)臺灣港務股份有限公司
臺中港務分公司「臺中港北側淤沙區漂飛沙整治第四期工程」

依 據 臺灣港務股份有限公司臺中港務分公司 113 年 4 月 30 日中港工字第 1134660
521 號函。

說 明 旨揭工程自即日起至 116 年 3 月 11 日於臺中港北側淤沙區實施，工程內容
包含延建定沙突堤工程、新建離岸堤工程及新建檔沙牆(含移設)工程等
，並於施工週邊設置浮燈標。

執行作業船舶為本國籍工作船詠城 1 號，施工範圍、浮標座標表及其他資
訊詳如附件。

非旨述計畫相關之工作船隻，請避開該區域，注意航行以策安全。

位 置 北緯 24°18'11.0" ，東經 120°30'18.6" 。
北緯 24°18'02.9" ，東經 120°30'17.9" 。
北緯 24°17'54.8" ，東經 120°30'17.2" 。
北緯 24°18'10.7" ，東經 120°30'24.2" 。
北緯 24°18'02.5" ，東經 120°30'23.4" 。
北緯 24°17'54.3" ，東經 120°30'22.7" 。
北緯 24°18'49.8" ，東經 120°31'00.9" 。
北緯 24°18'45.6" ，東經 120°30'57.7" 。
北緯 24°18'41.3" ，東經 120°30'54.6" 。
北緯 24°18'37.1" ，東經 120°30'51.5" 。
北緯 24°18'32.9" ，東經 120°30'48.4" 。
北緯 24°18'28.6" ，東經 120°30'45.3" 。
北緯 24°18'24.4" ，東經 120°30'42.2" 。
北緯 24°18'20.2" ，東經 120°30'39.0" 。
北緯 24°18'15.9" ，東經 120°30'35.9" 。
北緯 24°18'11.7" ，東經 120°30'32.8" 。
北緯 24°18'07.4" ，東經 120°30'29.7" 。
北緯 24°18'03.2" ，東經 120°30'26.6" 。
北緯 24°17'59.0" ，東經 120°30'23.5" 。
北緯 24°17'54.7" ，東經 120°30'20.3" 。
北緯 24°18'11.0" ，東經 120°30'18.6" 。
北緯 24°18'02.9" ，東經 120°30'17.9" 。
北緯 24°17'54.8" ，東經 120°30'17.2" 。
北緯 24°18'10.7" ，東經 120°30'24.2" 。
北緯 24°18'02.5" ，東經 120°30'23.4" 。
北緯 24°17'54.3" ，東經 120°30'22.7" 。
北緯 24°18'49.8" ，東經 120°31'00.9" 。
北緯 24°18'45.6" ，東經 120°30'57.7" 。
北緯 24°18'41.3" ，東經 120°30'54.6" 。
北緯 24°18'37.1" ，東經 120°30'51.5" 。
北緯 24°18'32.9" ，東經 120°30'48.4" 。
北緯 24°18'28.6" ，東經 120°30'45.3" 。
北緯 24°18'24.4" ，東經 120°30'42.2" 。
北緯 24°18'20.2" ，東經 120°30'39.0" 。
北緯 24°18'15.9" ，東經 120°30'35.9" 。
北緯 24°18'11.7" ，東經 120°30'32.8" 。
北緯 24°18'07.4" ，東經 120°30'29.7" 。
北緯 24°18'03.2" ，東經 120°30'26.6" 。
北緯 24°17'59.0" ，東經 120°30'23.5" 。
北緯 24°17'54.7" ，東經 120°30'20.3" 。 *WGS84

交通部航港局局長
葉 協 隆



NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

May 1, 2024

232 Design and Construction Supervision Service for Sand Drift Reduced Works in North Beach of Taichung Harbor(Stage 4)

Source Port of Taichung, Taiwan International Ports Co. Ltd., No. 1134660521 dated April 30, 2024.

Details Sand drift reduced works are expected to be completed on March 11, 2027. Mariners are advised to navigate with caution in the area. Please refer to the attachment for more details.

Positions Lat. 24°18'11.0" N., Long. 120°30'18.6" E.
Lat. 24°18'02.9" N., Long. 120°30'17.9" E.
Lat. 24°17'54.8" N., Long. 120°30'17.2" E.
Lat. 24°18'10.7" N., Long. 120°30'24.2" E.
Lat. 24°18'02.5" N., Long. 120°30'23.4" E.
Lat. 24°17'54.3" N., Long. 120°30'22.7" E.
Lat. 24°18'49.8" N., Long. 120°31'00.9" E.
Lat. 24°18'45.6" N., Long. 120°30'57.7" E.
Lat. 24°18'41.3" N., Long. 120°30'54.6" E.
Lat. 24°18'37.1" N., Long. 120°30'51.5" E.
Lat. 24°18'32.9" N., Long. 120°30'48.4" E.
Lat. 24°18'28.6" N., Long. 120°30'45.3" E.
Lat. 24°18'24.4" N., Long. 120°30'42.2" E.
Lat. 24°18'20.2" N., Long. 120°30'39.0" E.
Lat. 24°18'15.9" N., Long. 120°30'35.9" E.
Lat. 24°18'11.7" N., Long. 120°30'32.8" E.
Lat. 24°18'07.4" N., Long. 120°30'29.7" E.
Lat. 24°18'03.2" N., Long. 120°30'26.6" E.
Lat. 24°17'59.0" N., Long. 120°30'23.5" E.
Lat. 24°17'54.7" N., Long. 120°30'20.3" E.
Lat. 24°18'11.0" N., Long. 120°30'18.6" E.
Lat. 24°18'02.9" N., Long. 120°30'17.9" E.
Lat. 24°17'54.8" N., Long. 120°30'17.2" E.
Lat. 24°18'10.7" N., Long. 120°30'24.2" E.
Lat. 24°18'02.5" N., Long. 120°30'23.4" E.
Lat. 24°17'54.3" N., Long. 120°30'22.7" E.
Lat. 24°18'49.8" N., Long. 120°31'00.9" E.
Lat. 24°18'45.6" N., Long. 120°30'57.7" E.
Lat. 24°18'41.3" N., Long. 120°30'54.6" E.
Lat. 24°18'37.1" N., Long. 120°30'51.5" E.
Lat. 24°18'32.9" N., Long. 120°30'48.4" E.
Lat. 24°18'28.6" N., Long. 120°30'45.3" E.
Lat. 24°18'24.4" N., Long. 120°30'42.2" E.
Lat. 24°18'20.2" N., Long. 120°30'39.0" E.
Lat. 24°18'15.9" N., Long. 120°30'35.9" E.
Lat. 24°18'11.7" N., Long. 120°30'32.8" E.
Lat. 24°18'07.4" N., Long. 120°30'29.7" E.
Lat. 24°18'03.2" N., Long. 120°30'26.6" E.
Lat. 24°17'59.0" N., Long. 120°30'23.5" E.
Lat. 24°17'54.7" N., Long. 120°30'20.3" E. *WGS84

*Director General Hsieh-Lung, Yeh
Maritime and Port Bureau, MOTC*