



交通部航港局航船布告

中華民國 113 年 11 月 12 日

715 於民國113年11月20日起至113年12月31日期間於下列位址連線範圍內進行海纜故障維修作業，請非旨述計畫相關之工作船隻，敬請避開該區域，注意航行以策安全。

依 據 依據內政部 113 年 11 月 11 日台內地字第 1130145846 號函辦理
說 明 位置：

北緯 25° 18.1557' N、東經 122° 07.0520'E；(WGS84)

北緯 25° 15.3930' N、東經 122° 15.3559'E；

北緯 25° 14.6366' N、東經 122° 30.4686'E；

北緯 25° 12.3543' N、東經 122° 29.9740'E；

北緯 25° 13.0461' N、東經 122° 14.6329'E；

北緯 25° 15.8503' N、東經 122° 06.0868'E。

位 置 北緯 25°18'09.3"，東經 122°07'31.2"。
北緯 25°15'23.6"，東經 122°15'21.4"。
北緯 25°14'38.2"，東經 122°30'28.1"。
北緯 25°12'21.3"，東經 122°29'58.4"。
北緯 25°12'21.3"，東經 122°29'58.4"。
北緯 25°15'51.0"，東經 122°06'05.2"。*WGS84

交通部航港局局長
葉協隆



NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

November 12, 2024

715

Cable Repair Operation will be undertaken on November 20 to December 31, 2024, all vessels are prohibited from sailing the survey waters.

Source
Details

Taiwan Ministry of Interior Letter No. 1130145846 dated November 11, 2024

Position□

Lat. 25° 18.1557' N□Long. 122° 07.0520'E□(WGS84)

Lat. 25° 15.3930' N□Long. 122° 15.3559'E□

Lat. 25° 14.6366' N□Long. 122° 30.4686'E□

Lat. 25° 12.3543' N□Long. 122° 29.9740'E□

Lat. 25° 13.0461' N□Long. 122° 14.6329'E□

Lat. 25° 15.8503' N□Long. 122° 06.0868'E□

Positions

Lat. 25°18'09.3" N., Long. 122°07'31.2" E.

Lat. 25°15'23.6" N., Long. 122°15'21.4" E.

Lat. 25°14'38.2" N., Long. 122°30'28.1" E.

Lat. 25°12'21.3" N., Long. 122°29'58.4" E.

Lat. 25°12'21.3" N., Long. 122°29'58.4" E.

Lat. 25°15'51.0" N., Long. 122°06'05.2" E. *WGS84

Director General Hsieh-Lung□Yeh
Marine and Port Bureau□MOTC