



## 交通部航港局航船布告

中華民國 114 年 2 月 7 日

48

礙航公告(北區)-轉新世紀資通股份有限公司114年2月12至114年3月15日於跨太平洋高速海纜(FASTER)區段六故障地點進行緊急搶修作業

依據 依據新世紀資通股份有限公司 114 年 2 月 6 日速博(發)字第 11440200369 號辦理。

說明 一、作業日期、時間： 114 年 2 月 12 日至 114 年 3 月 15 日，時間詳見附件。

二、作業地點：跨太平洋高速海纜(FASTER)區段六故障地點，位置約為 25°18.140' N、122°03.705' E，實際作業範圍將於確定故障位置後調整。

三、航行船隻，請避開該區域，注意航行以策安全。

四、有關旨案最新航船布告相關資訊，請至航港局局網「訊息發布」-「航船布告」-「全部」(<https://www.motcmpb.gov.tw/Information/Notice?SiteId=1&NodeId=483>)，建議隨時瀏覽，預為規劃。

位置 北緯 25°29'13.1"，東經 121°40'06.9"。  
北緯 25°24'08.8"，東經 121°38'25.3"。  
北緯 25°14'15.1"，東經 122°06'29.2"。  
北緯 25°19'24.0"，東經 122°07'54.3"。\*WGS84

交通部航港局  
局長 葉協隆



## NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

---

February 7, 2025

**48** Taiwan Northeast Waters –operations

Source NEW CENTURY INFOCOMM TECH CO,LTD,letter No. 11440200369 dated February 6, 2025.

Details 1.Emergency repair operation will take place from Feb. 12, 2025 to Mar. 15, 2025  
.  
2.During the operation period, all vessels are prohibited from sailing the operation waters.

Positions Lat. 25°29'13.1" N., Long. 121°40'06.9" E.  
Lat. 25°24'08.8" N., Long. 121°38'25.3" E.  
Lat. 25°14'15.1" N., Long. 122°06'29.2" E.  
Lat. 25°19'24.0" N., Long. 122°07'54.3" E. \*WGS84

*Maritime and Port Bureau, MOTC  
Director-General Yeh Hsieh-Lung*