



交通部航港局航船布告

中華民國 112 年 8 月 8 日

493

高雄港第二港口堤口附近海域海底發現疑似沉沒貨櫃

依據 臺灣港務股份有限公司高雄港務分公司 112 年 8 月 7 日高港港字第 11265922 89 號函

說明 一、高雄港務分公司針對高雄港二港口水域與航道以多音束側掃聲納進行檢視，經掃側作業後於水下約 22 公尺至 23 公尺發現疑似 6 只貨櫃沉沒於海床，其中有 5 只在航道中，惟不影響最大船型進出港作業，暫無礙航疑慮，該分公司將於海象許可時進行處理。為確保船舶進出港安全，請過往船隻注意，並請附近海域航行之船隻注意瞭望並避讓，以維航行安全，如有發現礙航物，請通報高雄港 VTS 信號台。

二、沉沒海床貨櫃 6 只經緯度如下 (座標系統 WGS-84):

(一) 北緯 22 度 33 分 00.72 秒；東經 120 度 16 分 53.57 秒。

(二) 北緯 22 度 32 分 57.38 秒；東經 120 度 16 分 55.74 秒。

(三) 北緯 22 度 32 分 54.74 秒；東經 120 度 16 分 42.00 秒。

(四) 北緯 22 度 32 分 47.46 秒；東經 120 度 16 分 46.85 秒。

(五) 北緯 22 度 32 分 39.34 秒；東經 120 度 16 分 52.92 秒。

(六) 北緯 22 度 32 分 33.13 秒；東經 120 度 16 分 47.83 秒。

三、聯絡人及電話如下：

(一) 高雄港務分公司港務處航管中心第二信號台：07-5711369#309。

(二) 高雄港務分公司港務處監控中心值勤室：07-5622127、07-5519018。

四、檢附「沉沒貨櫃位置圖」1 份。

位置 北緯 22°33'00.7"，東經 120°16'53.6"。
北緯 22°32'57.4"，東經 120°16'55.7"。
北緯 22°32'54.7"，東經 120°16'42.0"。
北緯 22°32'47.5"，東經 120°16'46.9"。
北緯 22°32'39.3"，東經 120°16'52.9"。
北緯 22°32'33.1"，東經 120°16'47.8"。*WGS84

交通部航港局
局長 葉協隆



NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

August 8, 2023

493

Discovery of Suspected Sunken Containers near the Breakwater Area of Kaohsiung Port Second Harbor.

Source
Details

TIPC Kaohsiung Harbor No. 1126592289

1. We would like to inform you that during a recent inspection in the waters and channels of Kaohsiung Port Second Harbor, using multibeam sidescan sonar, we detected what appears to be six sunken containers lying on the seabed at a depth of approximately 22 to 23 meters. Among these, five containers are located within the channel, but they do not obstruct the passage of the largest vessels entering or leaving the port. At present, there is no immediate risk to navigation, and we plan to address the situation when sea conditions permit.

2. The coordinates of the six sunken containers are as follows (WGS-84 coordinate system):

(a) Latitude 22 degrees 33 minutes 00.72 seconds; Longitude 120 degrees 16 minutes 53.57 seconds.

(b) Latitude 22 degrees 32 minutes 57.38 seconds; Longitude 120 degrees 16 minutes 55.74 seconds.

(c) Latitude 22 degrees 32 minutes 54.74 seconds; Longitude 120 degrees 16 minutes 42.00 seconds.

(d) Latitude 22 degrees 32 minutes 47.46 seconds; Longitude 120 degrees 16 minutes 46.85 seconds.

(e) Latitude 22 degrees 32 minutes 39.34 seconds; Longitude 120 degrees 16 minutes 52.92 seconds.

(f) Latitude 22 degrees 32 minutes 33.13 seconds; Longitude 120 degrees 16 minutes 47.83 seconds.

3. Contact person and phone number:

(a) Port Operations Center - Signal Station 2: 07-5711369#309.

(b) Port Operations Center - Monitoring Room: 07-5622127, 07-5519018.

4. Diagram including "Map of Sunken Container Locations" is attached to this announcement.

Positions

Lat. 22°33'00.7" N., Long. 120°16'53.6" E.

Lat. 22°32'57.4" N., Long. 120°16'55.7" E.

Lat. 22°32'54.7" N., Long. 120°16'42.0" E.

Lat. 22°32'47.5" N., Long. 120°16'46.9" E.

Lat. 22°32'39.3" N., Long. 120°16'52.9" E.

Lat. 22°32'33.1" N., Long. 120°16'47.8" E. *WGS84

*Director General of Maritime and Port Bureau
Yeh, Hsieh-Lung*