

礙船公告(南區)

「N-WH 計畫」堤防及浚挖工程-「一港口新南堤」完成沉箱定位資料相關資訊

依據：


說明：旨揭「N-WH 計畫」堤防及浚挖工程案完成「一港口新南堤」沉箱定位，航經本水域船隻請注意避讓。

Caissons are permanently installed within area bounded by the following position. Mariners are advised to navigate with caution in the area

位置：北緯 22° 41' 26.98"，東經 120° 15' 25.29"  
北緯 22° 41' 27.22"，東經 120° 15' 24.79"  
北緯 22° 41' 25.86"，東經 120° 15' 23.69"  
北緯 22° 41' 30.56"，東經 120° 14' 49.68"  
北緯 22° 41' 45.97"，東經 120° 14' 32.90"  
北緯 22° 41' 45.51"，東經 120° 14' 32.42"  
北緯 22° 41' 29.95"，東經 120° 14' 49.36"  
北緯 22° 41' 25.19"，東經 120° 15' 23.85" (WGS84)

Position : 22° 41' 26.98"N , 120° 15' 25.29"E  
22° 41' 27.22"N , 120° 15' 24.79"E  
22° 41' 25.86"N , 120° 15' 23.69"E  
22° 41' 30.56"N , 120° 14' 49.68"E  
22° 41' 45.97"N , 120° 14' 32.90"E  
22° 41' 45.51"N , 120° 14' 32.42"E  
22° 41' 29.95"N , 120° 14' 49.36"E  
22° 41' 25.19"N , 120° 15' 23.85"E (WGS84)





點位	E	N	WGS84	
1	173662.161	2510239.059	120° 15' 25.29"	22° 41' 26.98"
2	173647.815	2510246.618	120° 15' 24.79"	22° 41' 27.22"
3	173616.251	2510204.926	120° 15' 23.69"	22° 41' 25.86"
4	172646.330	2510354.388	120° 14' 49.68"	22° 41' 30.56"
5	172169.878	2510830.762	120° 14' 32.90"	22° 41' 45.97"
6	172155.882	2510816.757	120° 14' 32.42"	22° 41' 45.51"
7	172637.099	2510335.725	120° 14' 49.36"	22° 41' 29.95"
8	173620.639	2510184.215	120° 15' 23.85"	22° 41' 25.19"

