



交通部航港局航船布告

中華民國 113 年 7 月 11 日

408

礙航公告(中區)(更新編號第20240193號布告)(展延至113年9月30日)彰芳/西島風力發電股份有限公司「彰芳暨西島離岸風場之風場維護作業」相關資訊

依據 彰芳風力發電股份有限公司 113 年 7 月 9 日彰芳風力字第 1130709006 號函及西島風力發電股份有限公司 113 年 7 月 9 日西島風力字第 1130709007 號函。

說明 旨揭公司擬於 113 年 4 月 27 日至 113 年 9 月 30 日，以挪威籍補給船澳大利亞 (NORMAND AUSTRALIS) 執行風場維護作業。

非計畫相關之工作船隻請避開該區域，注意航行以策安全，相關資料詳如附件。

位置 北緯 24°02'46.3"，東經 120°12'49.0"。
北緯 23°57'29.1"，東經 120°08'57.3"。
北緯 23°57'50.1"，東經 120°03'59.1"。
北緯 24°02'44.1"，東經 120°07'46.8"。
北緯 23°59'04.5"，東經 120°11'06.3"。
北緯 23°58'52.7"，東經 120°12'20.5"。
北緯 23°58'43.1"，東經 120°12'13.9"。
北緯 23°58'02.0"，東經 120°11'43.1"。
北緯 23°57'11.3"，東經 120°10'58.3"。
北緯 23°57'04.8"，東經 120°10'52.1"。
北緯 23°57'15.4"，東經 120°09'46.6"。*WGS84

交通部航港局局長
葉協隆



NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

July 11, 2024

408

Changhua Taiwan Offshore-CFXD Offshore Wind Farm Maintenance Inspections

Source

Changfang Wind Power Co., Ltd., letter No. 1130709006 dated July 9, 2024.
Xidao Wind Power Co., Ltd., letter No. 1130709007 dated July 9, 2024.

Details

Mariners are advised that Changfang and Xidao Offshore Wind Farm shall commence maintenance inspections on or around April 27, and works are expected to be completed on September 30, 2024.

Mariners are advised to navigate with caution in the area.

Please refer to the attachment for more details.

Positions

Lat. 24°02'46.3" N., Long. 120°12'49.0" E.
Lat. 23°57'29.1" N., Long. 120°08'57.3" E.
Lat. 23°57'50.1" N., Long. 120°03'59.1" E.
Lat. 24°02'44.1" N., Long. 120°07'46.8" E.
Lat. 23°59'04.5" N., Long. 120°11'06.3" E.
Lat. 23°58'52.7" N., Long. 120°12'20.5" E.
Lat. 23°58'43.1" N., Long. 120°12'13.9" E.
Lat. 23°58'02.0" N., Long. 120°11'43.1" E.
Lat. 23°57'11.3" N., Long. 120°10'58.3" E.
Lat. 23°57'04.8" N., Long. 120°10'52.1" E.
Lat. 23°57'15.4" N., Long. 120°09'46.6" E. *WGS84

Director General Hsieh-Lung, Yeh
Maritime and Port Bureau, MOTC