



交通部航港局航船布告

中華民國 113 年 8 月 1 日

495

礙航公告(中區)(即日起至116年2月15日)臺灣港務股份有限公司臺中港務分公司「臺中港填方區新建海堤工程」為進行沉箱拖放及增加戒護船與配合施工船作業

依據 臺灣港務股份有限公司臺中港務分公司 113 年 7 月 29 日中港工字第 1134209 648 號函。

說明 旨揭臺中港務分公司委託台灣世曦工程顧問股份有限公司及宏華營造股份有限公司即日起至 116 年 2 月 15 日止，執行沉箱拖放及增加戒護船與配合施工船作業。

非計畫相關之工作船隻請避開該區域，注意航行以策安全，相關資料詳如附件。

位置 請航經附近水域船舶注意避讓，以維航行安全。

北緯 24°14'31.3"，東經 120°28'39.2"。
北緯 24°14'31.0"，東經 120°28'46.1"。
北緯 24°17'16.5"，東經 120°28'56.3"。
北緯 24°17'16.9"，東經 120°28'49.4"。
北緯 24°17'19.3"，東經 120°30'09.8"。
北緯 24°17'17.0"，東經 120°30'12.8"。
北緯 24°17'14.8"，東經 120°30'13.7"。
北緯 24°17'10.3"，東經 120°30'24.3"。
北緯 24°17'12.1"，東經 120°30'29.7"。
北緯 24°17'10.3"，東經 120°30'33.9"。
北緯 24°17'03.5"，東經 120°30'30.5"。
北緯 24°17'03.1"，東經 120°30'29.2"。
北緯 24°17'04.5"，東經 120°30'25.8"。
北緯 24°17'05.7"，東經 120°30'25.3"。
北緯 24°17'06.8"，東經 120°30'25.9"。
北緯 24°17'12.4"，東經 120°30'12.5"。
北緯 24°14'28.3"，東經 120°28'25.5"。
北緯 24°14'33.9"，東經 120°28'28.2"。
北緯 24°14'39.0"，東經 120°28'30.7"。
北緯 24°14'44.0"，東經 120°28'33.4"。
北緯 24°15'15.5"，東經 120°28'51.5"。
北緯 24°15'28.3"，東經 120°28'57.4"。
北緯 24°17'19.4"，東經 120°30'11.6"。
北緯 24°17'14.8"，東經 120°30'32.1"。
北緯 24°17'13.0"，東經 120°30'36.2"。
北緯 24°17'11.1"，東經 120°30'40.1"。*WGS84

交通部航港局局長
葉協隆



NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

August 1, 2024

495 Seawall Construction Work in the landfill-area of Taichung Port

Source Port of Taichung, Taiwan International Ports Corporation Ltd., No. 1134209648 dated July 29, 2024.

Details Taichung Port will carry out operations to drag and drop caissons and increase guard ships and cooperating construction ships until February 15, 2027. Mariners are advised to navigate with caution in the area. Please refer to the attachment for more details.

Positions Lat. 24°14'31.3" N., Long. 120°28'39.2" E.
Lat. 24°14'31.0" N., Long. 120°28'46.1" E.
Lat. 24°17'16.5" N., Long. 120°28'56.3" E.
Lat. 24°17'16.9" N., Long. 120°28'49.4" E.
Lat. 24°17'19.3" N., Long. 120°30'09.8" E.
Lat. 24°17'17.0" N., Long. 120°30'12.8" E.
Lat. 24°17'14.8" N., Long. 120°30'13.7" E.
Lat. 24°17'10.3" N., Long. 120°30'24.3" E.
Lat. 24°17'12.1" N., Long. 120°30'29.7" E.
Lat. 24°17'10.3" N., Long. 120°30'33.9" E.
Lat. 24°17'03.5" N., Long. 120°30'30.5" E.
Lat. 24°17'03.1" N., Long. 120°30'29.2" E.
Lat. 24°17'04.5" N., Long. 120°30'25.8" E.
Lat. 24°17'05.7" N., Long. 120°30'25.3" E.
Lat. 24°17'06.8" N., Long. 120°30'25.9" E.
Lat. 24°17'12.4" N., Long. 120°30'12.5" E.
Lat. 24°14'28.3" N., Long. 120°28'25.5" E.
Lat. 24°14'33.9" N., Long. 120°28'28.2" E.
Lat. 24°14'39.0" N., Long. 120°28'30.7" E.
Lat. 24°14'44.0" N., Long. 120°28'33.4" E.
Lat. 24°15'15.5" N., Long. 120°28'51.5" E.
Lat. 24°15'28.3" N., Long. 120°28'57.4" E.
Lat. 24°17'19.4" N., Long. 120°30'11.6" E.
Lat. 24°17'14.8" N., Long. 120°30'32.1" E.
Lat. 24°17'13.0" N., Long. 120°30'36.2" E.
Lat. 24°17'11.1" N., Long. 120°30'40.1" E. *WGS84

Director General Hsieh-Lung, Yeh
Maritime and Port Bureau, MOTC