



交通部航港局航船布告

中華民國 113 年 10 月 29 日

685

礙航公告(中區)(展延至113年12月31日)海龍二號及海龍三號風電股份有限公司「海龍二號暨海龍三號離岸風力發電計畫執行海纜鋪設作業」

依 據 海龍二號風電股份有限公司 113 年 10 月 28 日海二電字第 2024102801 號函及海龍三號風電股份有限公司 113 年 10 月 28 日海三電字第 2024102801 號函。

說 明 旨案原訂於 113 年 11 月 30 日完成，惟考量海氣象等因素爰預計展延至 113 年 12 月 31 日止。

非計畫相關之工作船隻請避開該區域，注意航行以策安全，相關資料如附件

位 置 北緯 23°58'08.4" ，東經 119°48'49.7" 。
北緯 24°02'38.4" ，東經 119°51'26.3" 。
北緯 24°02'40.2" ，東經 119°55'40.1" 。
北緯 23°57'01.4" ，東經 119°51'18.7" 。
北緯 24°02'33.0" ，東經 119°40'53.4" 。
北緯 24°01'49.4" ，東經 119°40'34.7" 。
北緯 23°58'08.4" ，東經 119°48'49.7" 。
北緯 24°02'38.4" ，東經 119°51'26.3" 。
北緯 24°06'59.4" ，東經 120°23'47.0" 。
北緯 24°07'12.3" ，東經 120°22'47.6" 。
北緯 24°07'14.4" ，東經 120°20'35.5" 。
北緯 24°07'48.0" ，東經 120°18'01.8" 。
北緯 24°07'48.6" ，東經 120°17'58.6" 。
北緯 24°07'50.0" ，東經 120°17'55.7" 。
北緯 24°08'02.3" ，東經 120°16'46.2" 。
北緯 24°08'02.8" ，東經 120°16'38.6" 。
北緯 24°08'01.6" ，東經 120°16'12.4" 。
北緯 24°08'01.0" ，東經 120°16'01.6" 。
北緯 24°07'47.7" ，東經 120°10'48.7" 。
北緯 24°08'07.6" ，東經 120°10'18.8" 。
北緯 24°02'44.2" ，東經 119°55'50.9" 。
北緯 24°02'44.2" ，東經 119°55'43.3" 。
北緯 24°02'27.9" ，東經 119°55'30.4" 。
北緯 24°02'04.3" ，東經 119°55'12.4" 。
北緯 24°02'11.8" ，東經 119°55'58.1" 。
北緯 24°07'30.7" ，東經 120°10'13.8" 。
北緯 24°07'14.4" ，東經 120°10'38.3" 。
北緯 24°07'35.9" ，東經 120°16'36.1" 。
北緯 24°07'42.0" ，東經 120°16'41.9" 。
北緯 24°07'30.0" ，東經 120°17'48.1" 。
北緯 24°07'26.7" ，東經 120°17'53.2" 。
北緯 24°06'56.9" ，東經 120°20'28.0" 。
北緯 24°06'54.7" ，東經 120°22'46.6" 。
北緯 24°06'42.8" ，東經 120°23'38.4" 。
北緯 24°06'52.0" ，東經 120°23'43.1" 。 *WGS84

交通部航港局局長
葉 協 隆



NOTICE TO MARINERS

Published by Maritime Port Bureau, MOTC, R.O.C.

October 29, 2024

685 Changhua Taiwan Offshore-Hai Long 2 and Hai Long 3 Offshore Wind Farm
Subsea Cable Deployment

Source Hai Long 2 Offshore Wind Power Co., Ltd, letter No. 2024102801 dated October 28, 2024.

Hai Long 3 Offshore Wind Power Co., Ltd, letter No. 2024102801 dated October 28, 2024.

Details subsea cable deployment within Hai Long 2 and Hai Long 3 Offshore Wind Farm sites will be extended until December 31, 2024. Mariners are advised to navigate with caution in the area. Please refer to the attachment for more details.
Mariners are advised to navigate with caution in the area.
Please refer to the attachment for more details.

Positions Lat. 23°58'08.4" N., Long. 119°48'49.7" E.
Lat. 24°02'38.4" N., Long. 119°51'26.3" E.
Lat. 24°02'40.2" N., Long. 119°55'40.1" E.
Lat. 23°57'01.4" N., Long. 119°51'18.7" E.
Lat. 24°02'33.0" N., Long. 119°40'53.4" E.
Lat. 24°01'49.4" N., Long. 119°40'34.7" E.
Lat. 23°58'08.4" N., Long. 119°48'49.7" E.
Lat. 24°02'38.4" N., Long. 119°51'26.3" E.
Lat. 24°06'59.4" N., Long. 120°23'47.0" E.
Lat. 24°07'12.3" N., Long. 120°22'47.6" E.
Lat. 24°07'14.4" N., Long. 120°20'35.5" E.
Lat. 24°07'48.0" N., Long. 120°18'01.8" E.
Lat. 24°07'48.6" N., Long. 120°17'58.6" E.
Lat. 24°07'50.0" N., Long. 120°17'55.7" E.
Lat. 24°08'02.3" N., Long. 120°16'46.2" E.
Lat. 24°08'02.8" N., Long. 120°16'38.6" E.
Lat. 24°08'01.6" N., Long. 120°16'12.4" E.
Lat. 24°08'01.0" N., Long. 120°16'01.6" E.
Lat. 24°07'47.7" N., Long. 120°10'48.7" E.
Lat. 24°08'07.6" N., Long. 120°10'18.8" E.
Lat. 24°02'44.2" N., Long. 119°55'50.9" E.
Lat. 24°02'44.2" N., Long. 119°55'43.3" E.
Lat. 24°02'27.9" N., Long. 119°55'30.4" E.
Lat. 24°02'04.3" N., Long. 119°55'12.4" E.
Lat. 24°02'11.8" N., Long. 119°55'58.1" E.
Lat. 24°07'30.7" N., Long. 120°10'13.8" E.
Lat. 24°07'14.4" N., Long. 120°10'38.3" E.
Lat. 24°07'35.9" N., Long. 120°16'36.1" E.
Lat. 24°07'42.0" N., Long. 120°16'41.9" E.
Lat. 24°07'30.0" N., Long. 120°17'48.1" E.
Lat. 24°07'26.7" N., Long. 120°17'53.2" E.
Lat. 24°06'56.9" N., Long. 120°20'28.0" E.
Lat. 24°06'54.7" N., Long. 120°22'46.6" E.
Lat. 24°06'42.8" N., Long. 120°23'38.4" E.
Lat. 24°06'52.0" N., Long. 120°23'43.1" E. *WGS84

Director General Hsieh-Lung, Yeh
Maritime and Port Bureau, MOTC